LMA District Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard Eastern Honcut Creek

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)		
* Overall LMA Rating (Fall Only)						
	** Non-receipt of Su	mmer or Winter Inspe	ection Reports may effec	ct overall annual rating.		
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated	ratings are not detern			ual maintenance		
	FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.					
Comments						

Bank Unit Miles

Flood Control Project Maintenance Levee Inspections

Unit Cover Sheet

Spring 2010 Levee Inspection Results

Sutter Maintenance Yard Eastern Honcut Creek

Waterway

Unit No. 01 Van Tress Le						
	Spring (March - May)	Summer (June - August)	(September - November)		Winter ber - February)	
Unit Maintenance Rating (Fall Only)						
Date of Inspection	6/1/2010 - 6/1/2010					
DWR Inspector	Clay Thomas					
Accompanied By						
project components	vinter (or summer) inspection p identified in the attached Leve n the results of our normal mai	e Inspection Report by	Mile. We have found no chang	ges in flo		
During the current w project components maintenance and th following changes in	ed in the enclosed report. Vinter (or summer) inspection p identified in the attached Leve e corrections we have made to n flood project conditions. Cition below or on additional she n (Land Side, Water Side, or C	e Inspection Report by maintenance deficient eet(s), identify change of	Mile. In addition to the results cies identified in the report, we of condition by: Start to End Le	of our no have fou evee Mile	ormal und the or GPS	
Comments						
information must also be s	3	eet should be signed ar	d dated by the LMA Represen th 31 (Winter Inspection). Plea spection Reports , Room LL-30	tative an	d returned to	
x						
Signature of LMA Repres	sentative		Date			

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.50	06/01/2010 06/01/2010	Clay Thomas

LMR	Levee	Mile	Catagani	Item	Location	Rating	GPS Latitud		le/Longitude	Issue No.
No.	Start	End	Category	item	tion	ing *	Action/Comment	Start	End	Photo
1	0.01	1.45	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	39.298536 ° -121.569450 °	39.295243 ° -121.546944 °	7 Y
2	0.01	0.66	Earthen Levee	Vegetation	CR	М	Control annual grass and weeds on the levee slopes and easements.	39.298580 ° -121.569435 °	39.297615 ° -121.558343 °	
3	0.02	1.45	Earthen Levee	Vegetation	ws	М	Control annual grass and weeds on the levee slopes and easements.	39.298536 ° -121.569448 °	39.295245 ° -121.546941 °	
4	0.02	0.80	Earthen Levee	Crown Surface / Depressions / Rutting	CR	С	Add appropriate gravel or road base. Grade and compact.	39.298533 ° -121.569447 °	39.295887 ° -121.558138 °	
5	0.02	0.69	Earthen Levee	Crown Surface / Depressions / Rutting	CR	М	Add appropriate gravel or road base. Grade and compact.	39.298508 ° -121.569482 °	39.297368 ° -121.558311 °	
6	0.89	1.50	Earthen Levee	Crown Surface / Depressions / Rutting	CR	С	Add appropriate gravel or road base. Grade and compact.	39.294973 ° -121.557440 °	39.295257° -121.546386°	9

** Rating

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.50	06/01/2010 06/01/2010	Clay Thomas

Levee Mile Report Line	1		
Start Levee Mile	0.01		
End Levee Mile	1.45		
Location	Land Side		
Category	Earthen Levee		
Item	Vegetation		
Land side vegetation levee mile 0.05.			
cathom_s_20100610_110.jpg			

2
0.01
0.66
Crown
Earthen Levee
Vegetation
mile 0.05.

cathom_s_20100610_112.jpg

Levee Mile Report Line	3			
Start Levee Mile	0.02			
End Levee Mile	1.45			
Location	Water Side			
Category	Earthen Levee			
Item	Vegetation			
Water side vegetation levee mile 0.05.				
cathom_s_20100610_111.jpg				







** Rating

A : Acceptable PO : Pa M : Minimally Acceptable CO : Co U : Unacceptable N : No

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected C : Corrected W : Watch/Monitor

Levee Inspection Report By Mile - Spring 2010

Sutter Maintenance Yard Eastern Honcut Creek

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Van Tress	Left	1.50	06/01/2010 06/01/2010	Clay Thomas

	_		
Levee Mile Report Line	5		
Start Levee Mile	0.02		
End Levee Mile	0.69		
Location	Crown		
Category	Earthen Levee		
Item	Crown Surface /		
	Depressions / Rutting		
Levee crown surface depressions.			
cathom_s_20100610_113.jpg			

